

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program June 17, 2013

	10261		
Reviewed:	PMO		

Mine Name: Desert Sienna	Permit Number: S/015/0093	
Operator Name: Bown Stone Products	Inspection Date: June 11, 2 013	
Inspector(s): Wayne Western, Mike Bradley	Time: 1:30 - 1:50 pm	
Other Participants: none	Mine Status: ACT	
Weather Condition: clear sky 82 degrees	Last Inspection: June 20, 2012	
Bond Renewal Date: April 29, 2011	Bond Amount: April 29, 2011	
Surface Ownership: BLM	Mineral Ownership: BLM	
Last Year of Production: NA	Acreage: 5 acres	

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer,			
2.	Bond/Bond Release	\boxtimes	\boxtimes	
3.	Annual Fees			
4.	Annual Report			
5.	Public Safety (shafts, adits, trash, signs, highwalls)			
6.	Protection of Drainages / Erosion Control			
7.	Deleterious Material			
8.	Roads (maintenance, surfacing, dust control, safety)			
9.	Concurrent Reclamation			
10.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
11.	Water Impoundments			
12.	Soils			
13.	Re-vegetation			
14.	Air Quality			
15.	Other			

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond was scheduled for escalation on April 29, 2011. On January 28, 2013 the Division sent the Operator a letter reminding him that he had until February 28, 2013 to submit the bond. If the bond was not submitted by that the date the Division would issue a cessation order.

On May 13, 2013, the Division issued a cessation order and the Operator had until June 28, 2013 to provide additional surety or begin reclamation by than July 1, 2013 and finish no later than September 5, 2013.

Inspection Date: Page 2 of 4 M/000/0000

On June 6, 2013, the Operator submitted an application of bond release.

During the inspection, the Division found trash, equipment and stockpiles of stone.

Conclusions and Recommendations:

The site does not meet the minimum requirement for partial bond release. The Operator should finish reclaiming the site or post additional bond.

Wayer Water

Directions to Site:

Inspector's Signature

WHW:

cc: (OPERATOR)

ggochnour@blm.gov

O:\M015-Emery\S0150093-DesertSienna\inspections\insp-06112013.doc



Equipment and trash on site.



Trash on site



Equipment on site. Area has not been graded. No topsoil spread.



Equipment on site. Area has not been regarded.